

Turbine Problem Scenario

Problem:

Level-wind mechanism not controlling the tube follower



Turbine Problem Solutions

- Level-wind follower chain broken
- Level-wind Shear Stud that fastens Level-wind screw to sprocket shaft is missing or broken
- The Level-wind follower knife is damaged or missing

