

Turbine Problem Scenario

Problem:
Water leak behind turbine



Turbine Problem Solutions

- Water pressure insufficient to seal o-ring
- Bad or missing o-ring between stainless sleeve and turbine
- Defective weld between stainless sleeve and spool axle

