

Turbine Problem Scenario

Problem:
Gun cart tracks off to one side



Turbine Problem Solutions

- Gun cart not threaded into tube straight
- Tube not pulled out straight

