

Turbine Problem Scenario

Problem:
Tube will not pull out



Turbine Problem Solutions

- Is clutch pin disengaged on clutch Sprocket
- Spool brake adjusted too tight
- Tube has become crossed or tangled from coasting

