

# Water Leak on Spool Elbow Problem Scenario

---

## Problems:

- Leak on outside of Spool Bearing
- Leak on inside of Spool Bearing



# Water Leak on Spool Elbow Solutions

**If leak occurs on this side of bearing it is normally caused by bad threads on spool axle and/or spool nut. Another cause could be if the bonding agent has gone bad.**

