

Bellows Problem Scenario

Problem:

Water leaking behind the entry fitting



Bellows Problem Solutions

- The water pressure is insufficient to seal the o-ring
- Bad or missing o-ring between stainless sleeve and entry fitting

